

VEHICLE INSPECTION REPORT

Date Viewed: 5/2/09

Owner:	Council: NSW	Inspector: Graeme Richards	
Machine:	Johnston 605L/T		
Truck:	Hino FF		
Rego:	ZFG-454	Model:	FF
Tare:		Gross:	
Year:	03/98	Vin No:	JHDF1JGXXX10229
Serial No:		Engine No:	
Odometer:	182,517	Hour Meter:	9086
Transmission:	AT545		
Steer Control:	Single:	Dual:	Yes
Motor:	Oil	slight	
	Leaks:		
Hydraulic / Electric Tilt	Yes		
Cabin:	Aircon: Yes	Radio	Yes
Paint:	Good:	Fair: Fair	Bad:
Electric Windows:	NO	Seats	STD Hino
Tyres:	Front: 80%	Rear:	50%
Body:	Good:	Fair:	Bad: Rust in roof
	Lights: OK	Indicator: OK	Horn: OK
General Com:	Tidy unit but has rust in roof that is typical of this 1998 Low Top Model. See Pictures. Tidy cabin, dents around front bumper area on L/H side of cab.		
 Test Drive:			
Brakes:	OK		
Steering:	OK		
Transmission:	OK		
Dif:	OK		
General Com:			
 Sweeper:			
Engine Make:	Perkins	Model: Phaser	Hour Meter: 9086
Sweep:	Single:	Dual: Yes	Super Sweep:
Aux Motor:	Oil Leaks	NO	

Fan: Good: _____ Fair: **Yes** Bad: _____
 Hopper: Stainless: **Body** Rubber Lined: **no** Screen Chains: _____
 H/P Water: **NO** Front Spray Bar: _____
 Boost Spray Bar Behind L/P H/P Bottom Broom
 Nozzle: _____ H/P Spray Bar: _____
 Fan Wash: _____ H/Lance: _____ Detergent: _____
 CCTV: **B/W** Model: **Mistub**
 Camera: **Rear only** Gutter Broom Area _____

Seat Covers: _____
 Heated Electric Mirrors: **NO** WORKING LHS RHS
 Light Bar: **NO**
 Rotating Beacons: Front: **YES** Rear: _____
 Spigot Water: LHS **Yes** RHS
 Electric Tilt / Roto Tilt: LHS **YES** RHS
 Down Pressure LHS: **YES** RHS: _____ Wide Sweep /Bottom Broom: _____
 Weed Spray: LHS: **NO** RHS
 Shovel Holder: **YES** Broom Holder: _____ Hydrant Mount: _____
 Sunvisor: **Yes** Weather Shield: **NO** Tinted Windows: _____
 Overhead Boom: **6 inch spring type** Hydraulic Power Boom: **NO**
 Seals: Rear Door: **OK** Inspection Doors: **OK**

General Comments:
 Reasonable straight and tidy unit. Does have RUST damage to roof (see photos) as per typical
 1998 Johnston units.
 Some panel damage around front L/H side of cabin. Heavy duty 250kg crane mounted to rear
 Door as per attached photos. Tidy cabin interior and will clean up OK.

Suggested Trade Price: _____ Suggested Sale Price: _____

Signed By: Graeme Richards