

VEHICLE INSPECTION REPORT

Date Viewed: 21/01/2008

| | | |
|---------------------------|--|--|
| Owner: | Council: QLD Council | Inspector: Roger Howe |
| Machine: | MJE 770 Cyclone Regenerative | |
| Truck: | Hino FF | |
| Rego: | Sth Aust SB25AD | Model: FFIJGLA (A) |
| Tare: | 8700 | Gross: 13600 |
| Year: | 07/2002 | Vin No: JHDFFIJGLXXX10162 |
| Serial No: | S64.04 | Engine No: J08CF21538 |
| Odometer: | 123135 | Hour Meter: 9285 |
| Transmission: | Auto | |
| Steer Control: | Single: _____ | Dual: <input checked="" type="checkbox"/> |
| Motor: | Oil NO | |
| | Leaks: _____ | |
| Hydraulic / Electric Tilt | YES <input checked="" type="checkbox"/> | |
| Cabin: | Aircon: <input checked="" type="checkbox"/> | Radio / Cassette: <input checked="" type="checkbox"/> |
| Paint: | Good: <input checked="" type="checkbox"/> | Fair: _____ Bad: _____ |
| Electric Windows: | NO <input checked="" type="checkbox"/> | Seats ISRI / KAB / Standard <input checked="" type="checkbox"/> |
| Tyres: | Front: 70 % | Rear: 90% |
| Body: | Good: <input checked="" type="checkbox"/> | Fair: _____ Bad: _____ |
| | Lights: <input checked="" type="checkbox"/> | Indicator: <input checked="" type="checkbox"/> Horn: <input checked="" type="checkbox"/> |
| General Com: | First indications are that this machine has been serviced and well maintained in good operating condition. | |
| Test Drive: | | |
| Brakes: | Good | |
| Steering: | OK | |
| Transmission: | OK | |
| Dif: | OK | |
| General Com: | Drives well | |
| Sweeper: | | |
| Engine Make: | John Deere | Model: _____ Hour Meter: 6473 |
| Sweep: | Single: _____ | Dual: <input checked="" type="checkbox"/> Super Sweep: _____ |
| Aux Motor: | Oil Leaks No | |

