

**VEHICLE INSPECTION REPORT**

Date Viewed: 13/9/2007

Owner: Council: NSW Inspector: Graeme Richards

Machine: MacDonald Johnston 770 Cyclone

Truck: Hino Ranger Pro 8

Rego: SB66CE Model: FF

Tare: Gross: 13600

Year: 12/2002 Vin No: JHDFFIJGLXXX10202

Serial No: Engine No:

Odometer: 99,642 Hour Meter: 6,356

Transmission: Allison Auto

Steer Control: Single: Dual:

Motor: Oil None  
Leaks:

Hydraulic / Electric Tilt NO

Cabin: Aircon: Wall Mount red dot Radio / CD: Radio Cassette

Paint: Good:  Fair: Bad:

Electric Windows: NO Seats KAB

Tyres: Front: 90 % Rear: 70 %

Body: Good:  Fair: Bad:  
Lights:  Indicator:  Horn:

General Com: Straight reasonable unit. Some small dents kerbside front quarter panel + bar.

***Test Drive:***

Brakes:

Steering:

Transmission:

Dif:

General Com:

***Sweeper:***

Engine Make: John Deere Model: Hour Meter: 7,244

Sweep: Single: Dual:  Super Sweep:

Aux Motor: Oil Leaks slight

Fan:	Good: <input checked="" type="checkbox"/>	Fair: _____	Bad: _____
Hopper:	Stainless: <input checked="" type="checkbox"/>	Rubber Lined: _____	Screen Chains: <input checked="" type="checkbox"/>
H/P Water:	<input checked="" type="checkbox"/>	Front Spray Bar: _____	
Boost Spray Bar Behind Nozzle:	L/P H/P	H/P Bottom Broom Spray Bar:	Front of hood mounted
Fan Wash:	H/Lance: <u>Missing</u>	Detergent: _____	No
CCTV:	B & W	Model: _____	Mitsubishi
Camera:	Rear	Gutter Broom Area	YES right hand side only
Seat Covers:	NO		
Heated Electric Mirrors:	YES	WORKING	<input checked="" type="checkbox"/> LHS <input checked="" type="checkbox"/> RHS
Light Bar:	NO		
Rotating Beacons:	Front: <input checked="" type="checkbox"/>	Rear: <input checked="" type="checkbox"/>	
Spigot Water:	LHS	NO	RHS
Electric Tilt / Roto Tilt:	LHS <input checked="" type="checkbox"/>	RHS <input checked="" type="checkbox"/>	
Down Pressure	LHS: <input checked="" type="checkbox"/>	RHS: <input checked="" type="checkbox"/>	Wide Sweep /Bottom Broom:
Weed Spray:	LHS: NO	RHS: _____	
Shovel Holder: <input checked="" type="checkbox"/>	Broom Holder: <input checked="" type="checkbox"/>	Hydrant Mount: <input checked="" type="checkbox"/>	
Sunvisor: <input checked="" type="checkbox"/>	Weather Shield:NO	Tinted Windows: <input checked="" type="checkbox"/>	
Overhead Boom:	Rear door mounted	Hydraulic Power Boom: _____	
Seals:	Rear Door: _____	Inspection Doors: _____	
General Comments: Unit is very straight and tidy 2003 delivery, cut and polish will bring this unit Up very clean.			

Suggested Trade Price: \$ \_\_\_\_\_ Suggested Sale Price: \_\_\_\_\_

Signed By: \_\_\_\_\_