

VEHICLE INSPECTION REPORT

Date Viewed: 30/04/09

Owner: Council: SA Inspector: R.Hicks & W.Trimper

Machine: Scarab Major 5000 MKII / I

Truck: Leyland Daf

Rego: GVP 225 Model: 45-160 Ti

Tare: 5860kg Gross: 11,000kg

Year: 01/2000 Vin No: XLRAE45CEY1213644

Serial No: Engine No:

Odometer: 264031 Hour Meter: 20

Transmission: Manual 5 speed

Steer Control: Single: Dual: ✓

Motor: Oil Leaks: Minor power steering leak at reservoir, coolant leak at head tank

Hydraulic / Electric Tilt n/a

Cabin: Aircon: u/s Radio / CD: u/s

Paint: Good: Fair: ✓ Bad:

Electric Windows: NO Seats KAB – LHS / Standard RHS

Tyres: Front: 90 % Rear: 90 %

Body: Good: Fair: ✓ Bad:

Lights: ✓ Indicator: ✓ Horn: ✓

General Com: Overall average condition, minor attention required, presentable.

Test Drive:

Brakes: Good

Steering: Good

Transmission: Good

Dif: Good

General Com: Controls sensitive, firm ride

Sweeper:

Engine Make: Model: Hour Meter:

Sweep: Single: Dual: Super Sweep:

Aux Motor: Oil Leaks -

Fan: Good: Fair: _____ Bad: _____

Hopper: Stainless: _____ Rubber Lined: No Screen Chains: No

H/P Water: _____ Front Spray Bar:

Boost Spray Bar Behind L/P H/P Bottom Broom No
Nozzle: H/P No Spray Bar: _____

Fan Wash: No H/Lance: _____ Detergent: No

CCTV: B & W _____ Model: Mitsubishi

Camera: Rear _____ Gutter Broom Area NO

Seat Covers: _____

Heated Electric Mirrors: _____ WORKING LHS RHS

Light Bar: _____

Rotating Beacons: Front: Rear:

Spigot Water: LHS RHS

Electric Tilt / Roto Tilt: LHS RHS

Down Pressure LHS: _____ RHS: _____ Wide Sweep /Bottom Broom: _____

Weed Spray: LHS: _____ RHS: _____

Shovel Holder: Broom Holder: Hydrant Mount:

Sunvisor: _____ Weather Shield: _____ Tinted Windows: _____

Overhead Boom: _____ Hydraulic Power Boom: _____

Seals: Rear Door: Good Inspection Doors: Good

General Comments: _____

Good Fair Unit

Suggested Trade Price: \$ _____ Suggested Sale Price: \$ _____

Signed By: Rohan Hicks