

VEHICLE INSPECTION REPORT

Date Viewed: 27/11/08

Owner: Council: SA Inspector: Colin Miller

Machine: Scarab Major 5000

Truck: Leyland DAF

Rego: Unregistered Model: 45 series

Tare: 5,580 Gross: 10,000

Year: 10/2001 Vin No: SBLAE45CEOL145606

Serial No: Engine No:

Odometer: 92,183 Hour Meter: 13,118

Transmission: Manual (6) speed

Steer Control: Single: Dual:

Motor: Oil Leaks:

Hydraulic / Electric Tilt NO

Cabin: Aircon: Radio / Cassette:

Paint: Good: Fair: Bad:

Electric Windows: NO Seats ISRI

Tyres: Front: 80 % Rear: 80 %

Body: Good: Fair: Bad:

Lights: Indicator: Horn:

General Com: Cabin Clean and Tidy.

Goes in / out hydrostatic very well.

Cab / body clean no rust.

Test Drive:

Brakes:

Steering:

Transmission: New clutch and pressure plate 1 year ago

Dif:

General Com:

Sweeper:

Engine Make: - Model: - Hour Meter: 13 118

Sweep: Single: - Dual: Super Sweep: NO

Aux Motor: Oil Leaks -

Fan:	Good:	Fair:	✓	Bad:
Hopper:	Stainless:	✓	Rubber Lined:	Screen Chains:
H/P Water:	No	Front Spray Bar:	✓	
Boost Spray Bar Behind Nozzle:	L/P	✓	H/P Bottom Broom Spray Bar:	No
Fan Wash:	No	H/Lance:	No	Detergent:
CCTV:	B & W	✓	Model:	Mitsubishi 4inch
Camera:	Rear	✓	Gutter Broom Area	NO
Seat Covers:	YES			
Heated Electric Mirrors:	YES	WORKING	LHS	✓ RHS ✓
Light Bar:	YES			
Rotating Beacons:	Front:	✓	Rear:	✓
Spigot Water:	LHS	✓	RHS	No
Electric Tilt / Roto Tilt:	LHS	✓	RHS	No
Down Pressure	LHS:	✓	RHS: No	Wide Sweep /Bottom Broom: No
Weed Spray:	LHS: No	RHS: No		
Shovel Holder: No	Broom Holder: No	Hydrant Mount: No		
Sunvisor: ✓	Weather Shield: No	Tinted Windows: ✓		
Overhead Boom: rear mounted standard	Hydraulic Power Boom: No			
Seals:	Rear Door:	Needs replacement	Inspection Doors:	Needs replacement

General Comments: Fan vibration and slightly rusty on one blade.

Battery isolator, wash out hose, nozzle water, broom water, new screens 2 years ago in good condition, spill tray slightly bent, surface rust from hopper hinge left side.

Suggested Trade Price: _____ Suggested Sale Price: \$85k + GST

Signed By: _____ Colin