

## VEHICLE INSPECTION REPORT

Date Viewed: 20/08/09

Owner: Council: SA Inspector: Wade trimper

Machine: Scarab merlin

Truck: DAF 45/160 euro2

Rego: XEH 937 Model: FA45/160

Tare: 5.88 Gross: 11.0

Year: 2000 Vin No: XLRAE45CEYL219475

Serial No: Engine No:

Odometer: 243655 Hour Meter: 4515

Transmission: Manual 5 speed

Steer Control: Single: no Dual: Yes

Motor: Oil Minor coolant leaks  
Leaks:

Hydraulic / Electric Tilt Hydraulic tilt good working order

Cabin: Aircon: Not working Radio / CD: radio

Paint: Good: Fair: ✓ Bad:

Electric Windows: NO Seats LHS/Isri RHS/Isri

Tyres: Front: 65 % Rear: 90 %

Body: Good: Fair: ✓ Bad:

Lights: ✓ Indicator: ✓ Horn: ✓

General Com: Parking lights u/s

Rear clearance lights u/s

LHS rear indicator u/s

**Test Drive:**

Brakes: Serviceable

Steering: Serviceable

Transmission: Serviceable

Dif: Serviceable

General Com: No operational faults observed during inspection.

Drives well.

**Sweeper:**

Engine Make: n/a Model: n/a Hour Meter: n/a

Sweep: Single: Dual: ✓ Super Sweep:

Aux Motor: Oil Leaks n/a

